

PRODUCT-DETAILS

3BSM013241-A RTD Pt 100 ohm

General Information	
Product ID	3BSM013241-A
ABB Type Designation	RTD Pt 100 ohm
Catalog Description	RTD Pt 100 ohm
Ordering	
Ordering Country of Origin	United States (US)
Customs Tariff Number	85332100
Selling Unit of Measure	piece
Minimum Order Quantity	1 piece
Order Multiple	1 piece
Stocked At (Warehouses)	Västerås, Sweden

Additional Information

Technical Information

The RTD located in the exciter stator winding are not replaceable. As the exciter stator is impregnated it will get damaged, when trying to replace the exciter stator RTD's. Hence it is not recommended to use as spare parts, nor to consider replacing them. In case the RTD's are broken they must first be measured (which must be determined at terminal blocks inside the enclosure). If they indeed are broken then it must be replaced with a different part, in a total different way, which will require time and effort from our engineering department.

Categories